

# Kodak alaris Legacy Scanner Replacement Chart



Kodak Legacy Scanners					Current Kodak Alaris Scanner				
	PPM	PPD	ADF	Connectivity		PPM	PPD	ADF	Connectivity
<b>Kodak i30/i40 Scanners</b>	25	1K	50	USB 2.0	<b>Kodak i940/i2420/i2620/i2820</b>	20/40/60/70(BW) 60(Color)	500/5K/7K/8K	20/50/75/100	USB 2.0
<b>Kodak i50/i60/i80 Scanners</b>	20/25/35	1K/1K/1.5K	75	SCSI-2	<b>Kodak i940/i2420/i2620/i2820</b>	20/40/60/70(BW) 60(Color)	500/5K/7K/8K	20/50/75/100	USB 2.0
<b>Kodak i55/i65 Scanners</b>	36	1.5K	75	SCSI-2, USB 2.0	<b>Kodak i2420/i2620/i2820</b>	40/60/70(BW) 60(Color)	5K/7K/8K	50/75/100	USB 2.0
<b>Kodak i1200 Plus Series Scanners</b>	45(BW) 30(Color)	3K	75	USB 2.0	<b>Kodak i2420/i2620/i2820</b>	40/60/70(BW) 60(Color)	5K/7K/8K	50/75/100	USB 2.0
<b>Kodak i1300 Plus Series Scanners</b>	60(BW) 40(Color)	5K	75	USB 2.0	<b>Kodak i2420/i2620/i2820</b>	40/60/70(BW) 60(Color)	5K/7K/8K	50/75/100	USB 2.0
<b>Kodak i1400 Series Scanners</b>	45/60/75	7.5K/9K/ 12K/15K	150	USB 2.0	<b>Kodak i3200/i3400</b>	50/90	15K/20K	250	USB 2.0
<b>Kodak Digital Science Scanner 1500</b>	50	4.4K	200	SCSI-2	<b>Kodak i2420/i2620/i2820</b>	40/60/70(BW) 60(Color)	5K/7K/8K	50/75/100	USB 2.0
<b>Kodak Digital Science Scanner 2500</b>	60	4.4K	300	SCSI-2	<b>Kodak i2420/i2620/i2820 i3250/i3450</b>	40/60/70(BW) 60(Color)/ 50/90	5K/7K/8K 15K/20K	50/75/100/ 250/250	USB 2.0
<b>Kodak i250/i260/i280 Scanners</b>	67/50/81	5K/5K/7.5K	150	IEEE-1394	<b>Kodak i2420/i2620/i2820 i3200/i3250/i3400/i3450</b>	40/60/70(BW) 60(Color)/ 50/50/90/90	5K/7K/8K 15K/15K/20K/20K	50/75/100/ 250/250/250/250	USB 2.0
<b>Kodak Imagemlink Scanner 500</b>	60	12K	400	SCSI-2	<b>Kodak i425/i4650</b>	110/130	40K/75K	500/500	USB 3.0/USB 3.0
<b>Kodak Digital Science Scanners 3500/3510/3520/3590C</b>	75/75/85/85	10K/10K/ 20K/10K	150/150/ 250/150-250	SCSI	<b>Kodak i3400/ Kodak i4650/i4850/i5200</b>	90/130/150/140	20K/75K/125K/Unlimited	250/500/500/750	USB 2.0/USB 2.0/USB 3.0/ USB 2.0 Hi-Speed Cert.
<b>Kodak Digital Science Color Scanner 4500</b>	85	10K	250	SCSI	<b>Kodak i3400/ Kodak i4650/i4850/i5200</b>	90/130/150/140	20K/75K/125K/Unlimited	250/500/500/750	USB 2.0/USB 2.0/USB 3.0/ USB 2.0 Hi-Speed Cert.
<b>Kodak Digital Science Document Scanner 5500</b>	80	16K	200	SCSI-2	<b>Kodak i3400/ Kodak i4650/i4850/i5200</b>	90/130/150/140	20K/75K/125K/Unlimited	250/500/500/750	USB 2.0/USB 2.0/USB 3.0/ USB 2.0 Hi-Speed Cert.
<b>Kodak Imagemlink Scanner 900</b>	120	15K	300	SCSI-2	<b>Kodak i4850/i5200</b>	150/140	125K/Unlimited	500/750	USB 3.0/USB 2.0 Hi-Speed Cert.
<b>Kodak Digital Science Document Scanner/Microimager 990</b>	120	15K	300	SCSI-2	<b>Kodak i1860/i5600</b>	200/170	Unlimited/Unlimited	500/750	FireWire/USB 2.0 Hi-Speed Cert.
<b>Kodak Imagemlink Scanner 923</b>	144	15K	300	SCSI-2/RS-232	<b>Kodak i1860/i5850/i5600</b>	200/210/170	Unlimited/Unlimited/ Unlimited	500/750/750	FireWire/USB 2.0 Hi-Speed Cert./ USB 2.0 Hi-Speed Cert.
<b>Kodak 7500 Series Scanners</b>	120	24K	300	SCSI-2	<b>Kodak i4850/i5200</b>	150/140	125K/Unlimited	500/750	USB 3.0/USB 2.0 Hi-Speed Cert.
<b>Kodak 9500 Series Scanners</b>	160	33K	300	SCSI-2	<b>Kodak i1860/i5850</b>	200/210	Unlimited/Unlimited	500/750	FireWire/USB 2.0 Hi-Speed Cert.
<b>Kodak i610/i620/i640/i660 Scanners</b>	80/80/ 100/120	80K/80K/ 100K/120K	500	FireWire	<b>Kodak i4850/i5200</b>	150/140	125K/Unlimited	500/750	USB 3.0/USB 2.0 Hi-Speed Cert.
<b>Kodak i730/i750/i780 Scanners</b>	90/115/130	90K/115K/130K	500	FireWire	<b>Kodak i5600</b>	170	Unlimited	750	USB 2.0 Hi-Speed Cert.
<b>Kodak i810/i820 Scanners</b>	120	Unlimited	1K	SCSI-2	<b>Kodak i1860/i5600</b>	200/170	Unlimited/Unlimited	500/750	FireWire/USB 2.0 Hi-Speed Cert.
<b>Kodak i830/i840 Scanners</b>	160	Unlimited	1K	SCSI-2	<b>Kodak i1860/i5850</b>	200/210	Unlimited	500/750	FireWire/USB 2.0 Hi-Speed Cert.
<b>Kodak i1840 Scanner</b>	160	Unlimited	500	FireWire	<b>Kodak i1860/i5850</b>	200/210	Unlimited	500/750	FireWire/USB 2.0 Hi-Speed Cert.
<b>Kodak i4200 Scanner</b>	100	30K	500	USB 2.0	<b>Kodak i4250/i4650</b>	110/130	40K/75K	500/500	USB 3.0/USB 3.0

PPM = Pages Per Minute    PPD = Pages Per Day    ADF= Auto Document Feeder    FB = Flatbed


**BÖWE BELL+HOWELL** Legacy Scanner Replacement Chart

Böwe Bell + Howell Legacy Scanners					Current Kodak Alaris Scanner				
	PPM	PPD	ADF	Connectivity		PPM	PPD	ADF	Connectivity
<b>Copiscan 8000</b> (all models)					<b>Kodak Ngenuity 9090/9125/9150/ Kodak i5200V/i5600V/i5800</b>	90/125/150/ 140/170/210	90K/125K/150K/ Unlimited	700/ 750	USB 2.0; SCSI-3/ USB 2.0 Hi-Speed Cert.
<b>Copiscan II 6338/2138/3338</b>	50/ 72 Portrait/50	Unlimited	100/ 500 Option	SCSI/Video	<b>Kodak i3200/i3400</b>	50/90	15K/20K	250/250	USB 2.0
<b>Copiscan II 4040D</b>	40	4.5K	100	SCSI	<b>Kodak i3200/i3400</b>	50/90	15K/20K	250/250	USB 2.0
500FB	34	750	30	SCSI-2	<b>Kodak i3200/i3250/i3400/i3450</b>	50/50/90/90	15K/15K/20K/20K	250/250/250/250	USB 2.0
730DCFB	38	1K	50	SCSI-2/3	<b>Kodak i3200/i3250/i3400/i3450</b>	50/50/90/90	15K/15K/20K/20K	250/250/250/250	USB 2.0
1000FB	45	1.5K	100	SCSI-2	<b>Kodak i3200/i3250/i3400/i3450</b>	50/50/90/90	15K/15K/20K/20K	250/250/250/250	USB 2.0
2000FB/2000SFB/2000DFB	65	3K	150	SCSI-2	<b>Kodak i3200/i3250/i3400/i3450</b>	50/50/90/90	15K/15K/20K/20K	250/250/250/250	USB 2.0
2020DFB	65	3K	150	Video	<b>Kodak i3200/i3250/i3400/i3450</b>	50/50/90/90	15K/15K/20K/20K	250/250/250/250	USB 2.0
<b>Spectrum XF 8140DCI/8140DBI</b>	115/140	60K	500	SCSI-3	<b>Kodak Ngenuity 9150/Kodak i5600V</b>	150/170	150K/Unlimited	700/750	USB 2.0; SCSI-3/USB 2.0 Hi-Speed Cert.
<b>Spectrum XF 8120DC/8120DB</b>	90/120	60K	500	SCSI-3	<b>Kodak Ngenuity 9125/Kodak i4850/ Kodak i5200V</b>	125/150/140	125K/125K/Unlimited	700/500/750	USB 2.0; SCSI-3/USB 2.0 Hi-Speed Cert./ USB 3.0
<b>Spectrum XF 8090DC/8090DB/ 8090SC/8090SB</b>	70/90/ 70/90	60K	500	SCSI-3	<b>Kodak Ngenuity 9090/Kodak i4850/ Kodak i5200V/i4650 with VRS bundle</b>	90/150/140/130	90K/125K/Unlimited/75K	700/500/750/500	USB 2.0; SCSI-3/USB 2.0 Hi-Speed Cert./ USB 2.0/USB 3.0
<b>Spectrum 8125D-C-I/8125D-B-I</b>	125	60K	500	SCSI-3	<b>Kodak Ngenuity 9125/Kodak i4850/ Kodak i5200V</b>	125/150/140	125K/125K/Unlimited	700/500/750	USB 2.0; SCSI-3/USB 2.0 Hi-Speed Cert./ USB 3.0
<b>Spectrum 8100D-C-I/ 8100D-B-I/8100D-C/8100D-B</b>	100	60K	500	SCSI-3	<b>Kodak Ngenuity 9125/Kodak i4850/ Kodak i5200V/i4650 with VRS bundle</b>	125/150/140/130	125K/125K/Unlimited/75K	700/750/500/500	USB 2.0; SCSI-3/USB 2.0 Hi-Speed Cert./ USB 2.0/USB 3.0
<b>Spectrum 8080D-C-I/ 8080D-B-I/8080D-C/ 8080D-B/8080S-C-I/ 8080S-B-I/8080S-C/8080S-B</b>	80	60K	500	SCSI-3	<b>Kodak Ngenuity 9090/Kodak i4850/ Kodak i5200V/i4650 with VRS bundle</b>	90/150/140/130	90K/125K/Unlimited/75K	700/750/500/500	USB 2.0; SCSI-3/USB 2.0 Hi-Speed Cert./ USB 2.0/USB 3.0
<b>Trüper 3200</b>	62	10K	200	SCSI-3/USB 2.0	<b>Kodak i3250/i3450/ i4250 with VRS bundle (w/FB)</b>	50/90/110	15K/20K/40K	250/250/500	USB 2.0/USB 3.0
<b>Trüper 3600</b>	62	10K	200	USB 2.0	<b>Kodak i3200/i3400/ i4250 with VRS bundle</b>	50/90/110	15K/20K/40K	250/250/500	USB 2.0/USB 3.0
<b>Trüper</b>	62	10K	200	USB 2.0	<b>Kodak i3200/i3250/i3400/i3450</b>	50/90/100	15K/20K/30K	250/250/500	USB 2.0
<b>Sidekick 1200</b>	23 Portrait	4K	120	USB 2.0/SCSI-3	<b>Kodak i2420/i2620/i2820</b>	40/60/70(BW) 60(Color)	5K/7K/8K	75/100/100	USB 2.0
<b>Sidekick 1400</b>	43 Portrait	4K	120	USB 2.0/SCSI-3	<b>Kodak i2420/i2620/i2820</b>	40/60/70(BW) 60(Color)	5K/7K/8K	75/100/100	USB 2.0

PPM = Pages Per Minute

PPD = Pages Per Day

ADF= Auto Document Feeder

FB = Flatbed

